							=			~	10-		
	er ID 102099 2013 11:29:38 AM			*102		5M	P W	W-17	Page 1				
Item ID: D3183-045 Revision ID: Item Name: Bearing Assembly				Accept	*N900	)*	Setup	Start Stop	*N: *N:	57.2			
Start Date: Required Date: Reference:		<b>Qty:</b> 70.00 <b>Qty:</b> 70.00	*70* *70*		Cust Item I Customer:	D:							
Approvals:			Date: 13-5-24			ate:			Run	Start Stop	171	R1* R2*	
Sequence ID/ Work Center II	Opera D Descri			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept	Rej Qty		Reject Number	Insp. Stamp	= -
Draw Nbr	Revision N	br											
D3183	Rev C1									•		_	
*130 *130* Small Fab Small Fab	Small F	Memo	-5 Bearing into D3183-9 Ca	0.00 0.00 ap as per Dwg D3183.				70.	<u> </u>		7	J.3,	- 65 b
<sup>140</sup> <b>*1⊿∩*</b> <sup>QC</sup>	QC5- In	spect part comple Memo	eteness to step on W/O	0.00 13 5	÷27			70	\				
Quality Control  150  *150* Packaging	<b>Identify</b>	as per dwg & Sto	ck Location: 2357	B 0.00				700n	X			<b>S</b> D.	
Packaging		Memo		0.00								13-5-	<b>ラチ</b>

DQA:		Date:												
		_			WORK ORDER NON	-C(	ONFO	RMANCE / UP			*	,		AEROSPACE
QA Closed:		Date:								Wο	ork Order up	odate only	<u> </u>	
Work Orde	er:				DISPOSITION				AGAINST [	DEF	PARTMENT,	/PROCESS		
					Rework	1		Skid-tube	Crosstube			Water Jet	_	Engineering
Part N	No.				Scrap			Machining	Small Fab	$\dashv$	Pro	d. Eng. Coor.	$\Box$	Quality
					Use-as-is		1	noforming	Finishing	$\exists$		re/Packaging	<u> </u>	Other
NCR I	No				Suspected Unapproved	1	:	Large Fab	Composite	٦		Supplier		
						•							•	
Root				Desc	ription of work order update	Ī	Initial	Actio	on		Sign &			
Cause	Date	Step	Qty		or non-conformance	Ch	nief Eng	Descri	ption		Date	Verification	n	QC Inspector
Design														
Doc/Data														
Equip/Tooling			ļ							-				
Handling/Pre	$\square$		1											
Material														
Operator										i				
Offset/Setup														
Process														
Supplier	$\vdash$				,									
Training _	$\dashv$													
Transport	$\vdash$									-				
Unapproved			<u> </u>	<u> </u>										L
Londi						FAI	ULI CA	regory					—	
Landii	ng Gear	_		·	General		]		Г	7	0 1 1 1 5	. [	_	l
	Bending	3 Not Concei	ntrin	-	Bend BOM/Route		1	Program	<u> </u>	_	Outside Dim		_	Pressure/Forced
	Cracks	NOT COLICE	ntric		Broken/Damage/Defect		Grain		-	-1	Over/Under		_	Set-up
	—	(ink/Ripple	/\\\\				Hardwa		المالية المالية		Part Incorrec		_	Temperature/Cure
	Cuffs	ank) vibbie	:/ wave	<u> </u>	Burrs Contamination		1	ion Incomplete/Unc	· -	-	Part Lost/Mis	ssing	_	Weld
	Crushin	a		-	Countersink	-	4	ions Incomplete/Ur gned/off center	Licedi		Part Moved Positioned W	/rong		Wrong Stock Pulled
	Heat Tr				Cut Too Short	-	Mislabe		-	_	Power Loss/S			Other
	_	on Strip in	Tube		Drawing	_	Misread		L.		TOWEL LOSS/S	ouige [	—	Other
	Marks/	· · · · · · · · · · · · · · · · · · ·		-	Drill Holes	$\vdash$	Off-set	4		-	<u> </u>			
		Sequence			Finish	$\vdash$	1	Calibration		-			—	
ļ		wist in Tub			Fit/Function		1	Sequence		-	·	<del></del>		
								•						

0.00

Memo

**Quality Control** 

WF -27

## Picklist Print

Friday, May 24, 2013 11:29:37 AM

Work Order ID:

102099

Parent Item:

D3183-045

Parent Item Name:

Bearing Assembly

**Start Date:** 5/24/2013

Required Date: 5/29/2013

Page 1

**Start Qty:** 70.00

Required Qty: 70.00

Comments:

IPP A04.02.18New issueKJ/DS

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3183-9		Manufactured	No		····		Each	160.0000		70			1/. 7
Cap									C -5." • 6	— 6	7-2/5	105	127
				<b>Location</b>		Loc Qty	<u>Lo</u>	c Code			/ /	$\ell$	
				FG		5							
				89492	2	5							
				ST235		4							
				96380		1							
				98952	2	3			<del></del> -				
				ST235B	,	151			- 77	9			
				98952 99530		50 101			_4	<del>-121</del>			
D3183-5 Bearing		Manufactured	No	77030		110	Each	118.0000	1	~↓ <	S	3-/08	/27
				Location		Loc Qty	Lo	c Code			/ ,	/ /	
•				ST235B		118				/		•	
				98653	3	118			7	40"			


DQA:		Date:	:									<b>™</b> ∆A DT
QA Closed:		Date:			WORK ORDER NON	-C(	ONFO	RMANCE / UP		Vork Order up	ndate only	AEROSPACE
an closed.		Dute.					<del></del>	<del> </del>			· · · · · · · · · · · · · · · · · · ·	
Work Orde	er:				DISPOSITION				AGAINST D	EPARTMENT,	/PROCESS	
				_	Rework	]		Skid-tube	Crosstube		Water Jet	Engineering
Part I	No.				Scrap			Machining	Small Fab	Pro	d. Eng. Coor.	Quality
					Use-as-is		Therr	noforming	Finishing	Rec/Sto	re/Packaging	Other
NCR I	No				Suspected Unapproved	]		Large Fab	Composite		Supplier	
Poot	1		1	Doss	rintian of work arder undate		Initial	Acti		Cian 9	<u>-</u> .	
Root Cause	Da	ite Step	Qty	Desci	ription of work order update or non-conformance		initiai nief Eng	<u> </u>		Sign. & Date	Verification Processity	QC Inspector
Design	1 - D°	ite Step	Qty		or non-comormance	CI	ilei, Erig	Descri	μιση	Date	vernication	QC IIISPECTOI
Doc/Data	$\vdash$											·
Equip/Tooling		Ì										
Handling/Pre						-						
Material												
Operator												
Offset/Setup												
Process												
Supplier												
Training												
Transport												
Unapproved												
						FAI	ULT CAT	TEGORY				
Landi	ng Gear				General		_			<u></u>	_	
	Bend	ling			Bend		Folio/P	rogram		Outside Dim	ensions	Pressure/Forced
	Centi	re Not Conce	ntric		BOM/Route		Grain			Over/Under	tolerance	Set-up
	Crack				Broken/Damage/Defect		Hardwa	re		Part Incorred	t _	Temperature/Cure
	<b>—</b>	p/Kink/Ripple	e/Wave		Burrs		Inspecti	ion Incomplete/Und	qualified	Part Lost/Mi	ssing	Weld
	Cuffs				Contamination		1	ions Incomplete/U	nclear	Part Moved	L	Wrong Stock Pulled
	Crust				Countersink		1 -	ned/off center	<u>_</u>	Positioned V		
		Treat			Cut Too Short		Mislabe			Power Loss/	Surge	Other
		ection Strip in	Tube		Drawing		Misread	d				
	$\vdash$	s/Chatter			Drill Holes		Off-set					
		ing Sequence			Finish	$oxed{oxed}$	4	Calibration				
	Wave	e/Twist in Tul	be		Fit/Function_	•	Out of S	Sequence				

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH






CHECKED APPROVED DRAWING NO.  D3183 SH  DATE TITLE	<b>)</b>
	REV. C
04.02.17 BRACKET ASSEMBLY	SCALE




**DETAIL A (2:1)** 

**DEO ATTACHED** 

**DETAIL B (20:1)** 





## D3183-9 CAP

- 1) MATERIAL: DELRIN ROD, Ø1.00 (REF DART SPEC. M-DELRIN-R1.00)
- 2) TOLERANCES ARE PER DART QSI 018 **UNLESS OTHERWISE NOTED**
- 3) ALL DIMENSIONS ARE IN INCHES

## **D3183-045 BEARING ASSEMBLY**

1) ASSEMBLE D3183-5 BEARING AND D3183-9 CAP

COPYRIGHT © 2003 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.